



STATE OF WASHINGTON
GAMBLING COMMISSION

PO Box 42400 Olympia WA 98504-2400 (360) 486-3440 TDD (360) 486-3637 FAX (360) 486-3626

August 29, 2019

Jacqueline Hunter
Bally Technologies
6601 S Bermuda Road
Las Vegas, NV 89119

RE: Updated approval for MD3 Shuffler, Part Number 249498 and MD2299

Dear Ms. Hunter,

Pursuant to the recent approval of WAC 230-16-152, we are approving the MD3 Shuffler, Part Number 249498 which designates the MD3 Shuffler with the Flex Cellular Modem, and MD3 Shuffler, Part Number MD2299 which designates the MD3 Shuffler without the Flex Cellular Modem in Washington State.

The MD3 Shuffler, Part Number 249498 and MD3 Shuffler, Part Number MD2299, may be operated as a shuffler in Washington State. The approval is contingent on the following requirements:

Manufacturer Requirements:

- The two PIN numbers needed to access the shuffler's configuration and setup menu via the web interface are only to be used by Bally Gaming employees.
- No access should be given to the serial port of the device while on the live floor of the casino.
- Software signatures of the device should be verified with this approval letter before the MD3 Shuffler is put into play.
- The Enable Network setting in the Network Menu should be set to "Disabled" before the MD3 Shuffler is put into play to ensure the device is secure and avoid any potential security risks.
- When performing standard maintenance, all requirements of WAC 230-16-151 must be followed.



- The MD3 Shuffler should never be connected to any networking devices such as hubs, switches or routers.
- Any external tool connected to the MD3 Shuffler must have all wireless and Bluetooth functions disabled at all times during the connection.

Tribal Casino Implementation:

Ensure casino internal controls and game rules are revised to include this new equipment and procedures, and they are approved by the Tribal Gaming Agency and concurred with by the Washington State Gambling Commission.

The electronic signatures for the MD3 Shuffler are as follows:

Software Component	Signature Type	Signature
RNG_3.0.007	Kobetron	A1U5
MD3_Mico32_4.0.182 (installed)	SHA1	7D07C08C8C603BFE1575CE96ECF2DDB715307971
MD3_CardRec_4.1.008 (installed)	SHA1	DB3864E9A1EA97D05F2756B8744F325D7199CB9B
MD3_Mico32_4.0.182_setup.enc1	SHA1	18383C2D0291C1FF4DFC1B7E195BE8A1A02A162D
MD3_CardRec_4.1.008_setup.enc1	SHA1	F2BBEA255DB8D74D38B43E4715D76034CD131AD7
MD3_DeckLib_1.3.105_setup.enc1	SHA1	DDCFF91784133F2F6E836A765A6475FF9B72AAB3
MD3_Support_1.0.014_setup.enc1	SHA1	CD8F75FA8D009B54418A6A31DB36DF378DED4025

Any modifications made to the MD3 Shuffler must be submitted to us for additional testing and review. We reserve the right to investigate and reevaluate this equipment if we determine that such a review is necessary to ensure compliance with applicable compacts or laws in Washington.

Thank you for your cooperation during this process. We appreciate your desire to comply with our regulations. If you have any questions regarding this matter, please contact me at (360) 486-3546.

Sincerely,



Tina Griffin
Assistant Director
Licensing, Regulation, and Enforcement Division

cc: Cathy Harvey, Agent in Charge, Tribal Gaming Unit
Jim Nicks, Agent in Charge, Regulation Unit
File