



STATE OF WASHINGTON  
GAMBLING COMMISSION

*"Protecting the Public by Ensuring that Gambling is Legal and Honest"*

April 25, 2007

Mark Roy  
Shuffle Master  
1106 Palms Airport Drive  
Las Vegas, NV 89119

**RE: MD-2 Software Version 1.595 and Hardware Upgrade**

Dear Mr. Roy:

Thank you for submitting the MD-2 upgrades. A review was conducted and it was determined the MD-2 upgrades are suitable for installation in Washington. This approval is based on the information provided by Shuffle Master for this review.

The electronic signature for the MD-2 Shuffler is as follows:

Software Component	Device	Kobetron Signature
MD2 V 1.595	EPROM	9212

If any additional modifications are made to the MD-2, the software and associated equipment must be submitted for additional testing and review.

Thank you for your cooperation during this process. We appreciate your desire to comply with our regulations. If you have any questions regarding this matter, please contact me at (360) 486-3512.

Sincerely,

Dave Trujillo  
Assistant Director  
Licensing Operations Division

