



**STATE OF WASHINGTON  
GAMBLING COMMISSION**

*"Protect the Public by Ensuring that Gambling is Legal and Honest"*

October 9, 2023

*Sent via email to [Andrew@cammegh.com](mailto:Andrew@cammegh.com)*

Andrew Cammegh  
Old Surrenden Manor Road  
Kent, England  
TN26 3DL  
United Kingdom

RE: Submission # 3112 Cammegh Mercury 360 Wheel with Halo Band and #3113 Billboard Display v. 2.1

Dear Mr. Cammegh,

Thank you for requesting approval of Cammegh Mercury 360 Wheel with Halo Band (#3112) and the Cammegh Billboard Display v. 2.1 (#3113). We have completed our review. The Cammegh Mercury 360 Wheel with Halo Band and Cammegh Billboard Display v. 2.1 is approved for use in Washington State Tribal Casinos.

Approval of the Cammegh Mercury 360 Wheel with Halo Band and Cammegh Billboard Display v. 2.1 are contingent on the following requirements:

Manufacturer Requirements:

- Provide information to the tribal casino to keep the rotor speed between 10-30rpm for accurate display and recording of ball drops/outcomes.
- The keyboard and mouse must be disconnected from the billboard controller during play.
- Ensure all unused open ports on the Break Out Box (BOB) and CPC box are disabled or blocked from use.
- The Spread Bet side wager is not approved for use at this time.

Tribal Casino Implementation:

- Ensure internal controls and or game rules are revised to include new equipment, and procedures and are approved by the Tribal Gaming Agency and concurred with by the Washington State Gambling Commission.

**4565 7<sup>th</sup> Avenue SE, Lacey, WA 98503  
P.O. Box 42400, Olympia, WA 98504 | (360) 486-3440  
901 N. Monroe St., Suite 240, Spokane, WA 99201 | (509) 325-7900  
[wsgc.wa.gov](http://wsgc.wa.gov)**

Andrew Cammegh

October 9, 2023

Page 2

- Ensure game rules are revised to include games approved for use with the Cammegh Mercury 360 Wheel and Billboard Display to be offered and are approved by the Tribal Gaming Agency and concurred with by the Washington State Gambling Commission.

The following version numbers are approved in this submission:

- Break Out Box (BOB) software version 1.69
- Guzunda software version 2.6.1

### **Signatures**

<b>File Name</b>	<b>SHA1 Signature</b>
Billboard2.exe	2A3A61426F7E434346D033694CBC93F1254522C0
Billboard Device Manager.exe	2F0E70DD8A13F0222D93FE99855BFBE815A4FD5C
Roulette Camera 37.dll	675C332EFB6FCF9A360489412B40C1D50C96951F
Roulette Camera 38.dll	265B9BC0117CB423D6ECFB69322780E7B11825EE

Any modifications made to the Cammegh Mercury 360 Wheel with Halo Band and Billboard Display v. 2.1 must be submitted to us for additional testing and review. We reserve the right to investigate and re-evaluate this equipment if we determine that such a review is necessary to ensure compliance with tribal state compacts or rules and laws of Washington.

Please notify Special Agent Julie Kerkof at [Julie.kerkof@wsgc.wa.gov](mailto:Julie.kerkof@wsgc.wa.gov) at least 2 weeks prior to any scheduled installation of the Cammegh Mercury 360 Wheel with Halo Band and Billboard Display v. 2.1 into a tribal casino.

Thank you for your cooperation during this process. We appreciate your desire to comply with our tribal state compacts and rules and laws of Washington. If you have any questions regarding this matter, please contact me at (425) 766-5779.

Sincerely,



Dan Wegenast  
Agent in Charge  
Tribal Gaming Unit